REMARKS/ARGUMENTS

The enclosed replacement drawing sheets for FIGS. 1-7 include formally drafted diagrams, numbering, etc.

No new matter has been entered by the above amendments.

The Applicant respectfully requests that the replacement drawing sheets be included in the application so that the patent issues with these replacement sheets.

Respectfully submitted,

McCarthy Tétrault LLP

Date: May 2, 2006

By

Joseph P. Conneely

Registration No. 54,883 Telephone: (416) 601-8179

Fax: (416) 868-0673


McCarthy Tétrault LLP Box 48, Suite 4700 66 Wellington Street West Toronto Dominion Bank Tower Toronto, Ontario, Canada M5K 1E6


AMENDMENTS TO THE DRAWINGS:


The attached sheets of drawings include changes to FIGS. 1-7. These sheets, which include FIGS. 1-7, replace the original sheets including FIGS. 1-7. In FIGS. 1-7, the hand drawn diagrams, numbering, etc., have been replaced with formally drafted diagrams, numbering, etc.

Attachment: Replacement Sheets (i.e., 1/7 to 7/7)

Annotated Sheets Showing Changes (i.e., 1/7 to 7/7)








MPLS Frame 312	
data	header 2ndLabel 1st Label
314	316 320 318

Fig. 3

Annotated Sheet

Drawing Made
Formal




rawins -Madr ATM network 102(2) 520 ATHOAH AIS SIZ 122(2) . tune | 204 594 Card full 500. MRS OAM FDI 510, 502 Figure S (00/ 150 MR'S 202 Metwork 104 156200 MPLSOAM BDI 516 508 HPLS Card 404(1) ATH/MPLS edgeswitch ATH Cared 400(1) ATH DAM ATI Retwork 102(i) 522

20943140.1

Annotated Sheet

Drawins Made Formal



Annotated Fig. 7 Made Unknown State 702 Defect Declared Defect Not Detected Defect Declared Defect State οK state 706 704 Defect Cleared

> MPLS OAM state Machine 604